Modifications Highlights for VR-401-B

• Legal Language

- Revised all language pertaining to "Single-wall AST" to just "AST"
- Page 1, added language for reason for revision VR-401-B
- Under required testing, "TP-201.1B, Static Torque of Rotatable Phase I Adaptors (October 8, 2003)" has been added.

Exhibit 1

- Page 1, added flange mount AST number and note for flange gasket material
- Page 2, added Buna and Viton seal option to non-rotatable product adapter
- Page 4, "Non-rotatable vapor adaptor" changed to "Vapor Adaptor" to include bronze rotatable and non-rotatable adaptors
- ❖ Page 4, added OPW 1711LPC-0300 vapor dust cap
- Added "6211R Remote Spill Containers" to Table 1
- Page 8, added picture of flange emergency vent
- Page 16, added picture of bronze non-rotatable adaptor
- Page 17, added picture of bronze rotatable adaptor
- Page 18, added picture of ductile iron dust cap

Exhibit 2

- Page 1, revised non-rotatable heading and description to include rotatable vapor adaptors. Also added TP-201.1B test for rotatable adaptors.
- ❖ Table 2-1, added row to include rotatable adaptor
- Page 7, added new configuration
- Page 8, added new configuration
- Page 14, added 1711LPC, 61VSA-1020-EVR
- Page 15, added 1711LPC, 61VSA-1020-EVR
- ❖ Page 16, added 1711LPC, 61VSA-1020-EVR

• Exhibit 3

- Page 1, Vapor recovery adaptor has been revised to include rotatable adaptor
- Page 2, Table 3-1, added rotatable adaptor standard

Exhibit 4 – No revision

Installation, Operation and Maintenance manual (IOM) for VR-401-B

- Revised IOM to reflect VR-401-B title/headers etc.
- Page ii, revised OPW contact information and webpage
- Section 4, added manual for OPW 61VSA series rotatable vapor adapter
- Section 8, added manual for OPW 1711LPC-0300 vapor cap
- Section 12, added statement and torque specs pertaining to OPW flange emergency vent valves